Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: SACRAMENTO 2-10H

Field Name: BROOKLYN Well File #: 23020

Date Incident:5/18/2016Time Incident:11:30Facility ID Number:County:WILLIAMSTwp: 155Rng: 98Sec: 10Qtr:

Location Description:

Submitted By: Shane Knuchel Received By:

Contact Person: Shane Knuchel

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

20 Barrels 15 Barrels 20 barrels

Oil Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/12/2016 Clean Up Concluded: 10/12/2016

Risk Evaluation:

None

Areal Extent:

All fluid contained on location.

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Standing fluid sucked up. Impacted material will be removed and replaced or treated in-situ.

Wastes Disposal Location: TBD

Agencies Involved: Notified Mark Bins NDIC 5/18/2016 3:50 PM CT by phone.

Updates

Date: 5/19/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC retains oversight

Date: 6/6/2016 Status: Correspondence Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated June 6, 2016.